



Бесцентровый шлифовальный станок 3Ш184А			Конс. № 3094		Винт	C-04-1758
OT Mex		Стаб 45		3,5	1:1	1
Бес. Маши. Лучи						

1. HRC 27...30.
 2. H14, h14, ±5T14/2.



63/11